

rdkb-20190530 Release Notes

This link describes the Features and Bug Fixes between the current Iteration Release (rdkb-20190530) and the previous Iteration Release (rdkb-20190426).

| Repo | Commit-id | Description | Category |
|-----------------------|-----------|--|-------------|
| meta-cmf/ | 7e31352 | Update configs to use rdkb-20190530 branch | NA |
| | c8fafd5 | Update configs to use nightly/20190530-rdk-dev branch | |
| | 50aa336 | Update configs to use rdk-dev-1905 branch | |
| | a3be2dd | Enable rdkat in builds | Feature |
| | 88409e6 | Add support for coverity | Enhancement |
| | 0371107 | Inherit coverity class in lxccpid recipe append | |
| | 0738a99 | Inherit coverity class in breakpad-wrapper recipe append | |
| | 31a7def | Enable mesh-agent | |
| | dc6e726 | Add CMF coverity bbclass | |
| | 27998bc | Update SRC_URI override for rdm | |
| | df80644 | Update gen-autoconf script for LXC and refapp components | |
| | 1ff2e40 | Remove sso dependency | |
| | 54e478a | RDKCMF-8527 Upstream latest version of lxc-container-generator | |
| meta-cmf-96boards/ | 1ebc9ff | hikey-32: Switch to whitelist readline for mediaclient, README updated | Enhancement |
| | 47f5d04 | hikey-32: User switch to whitelist parted for mediaclient, README added | |
| meta-cmf-broadband/ | c9d1dd9 | Add xupnp overrides for broadband builds | Feature |
| | 8734b79 | Add overrides to install GrantType php files | Enhancement |
| | 7204228 | Inherit coverity class in tdk-b recipe append | |
| | a4db705 | Remove sso dependency | Bug Fix |
| | 61c7832 | Add utopia as a dependency of xupnp | |
| | 101f97a | Update ccsp-xconf SRC_URI override | |
| meta-cmf-raspberrypi/ | d84cfb1 | REFPLTB-289: Reference Implementation (Broadband) of Liberty Containerization implementation on R-Pi | Feature |
| | 6b12e8d | Add support for coverity | Enhancement |
| | 9cd8c2e | Add support for coverity | |
| | 304d78d | RDKCMF-8527 Upstream latest version of lxc-container-generator | |
| | 0bf98e4 | RDKCOM-867: Ref Platform test coverage improvement | |
| | | | |

| | | | |
|------------------------|---------|--|-------------|
| | f2fbbf4 | REFPLTB-303,REFPLTB-304 : [TDK]RPI is not rebooting on factory reset | Bug Fix |
| | f9075bd | Enable xupnp for broadband | |
| | 331cb5e | Remove parodus2snmp recipe override | |
| | 16529d1 | RDKCMF-8285 Add rpi specific patch to websocket-ipplayer | |
| meta-rdk/ | 043e4bb | RDK-23264: Mechanism for Plugin Download Notification | Feature |
| | 7e768eb | RDK-21877 conditional CC | Enhancement |
| | 497a8d2 | RDK-23613: Conditional USB automount | |
| | d23ba2d | RDKALL-1274: c-ares dependency changes for quagga | |
| | b212e44 | RDKCMF-8527 Upstream latest version of lxc-container-generator | |
| | 012033f | RDKB-19385: Use OAUTH to replace POTD, phase 2 | |
| | d480ffb | Restore the order of package groups | Bug Fix |
| | 5b3a545 | RDKB-21216 : self heal to restart Parodus stuck connecting | |
| | af349db | RDKB-16508:Create functions to fetch the broadband information | |
| | 16c26b3 | RDKB-22499 : reset parodus token after 403 | |
| | dcf7f1b | RDKB-20903 : parodus re-registration failures | |
| | ddcad60 | RDKALL-1696: Txi6 3.7 release builds from stable2 are failing in Jenkins | |
| | 5a6f0cb | RDKALL-1305 : Add changes in Parodus to fetch themis token using libcurl | |
| meta-rdk-broadband/ | 0c8c3a5 | SetLED binary to set the LED behavior | Enhancement |
| | e22ab6d | Move Components to Generic Repos | |
| | 186815e | Use OAUTH to replace POTD, phase 2 | |
| | 4922253 | Recipe changes to pull notify enable changes from parodus2ccsp | Bug Fix |
| | 9ff8ea5 | RDK Apache Header on Dibbler GPLv2 Sourced File | |
| | 007227a | Make dibbler client scripts common across RDKBn | |
| | 624743d | XF3 devices showing SYS_INFO_WEBPA_Config_Corruption markers | |
| meta-rdk-bsp-emulator/ | 949600f | Add cov erity support in mfrilib-emulator | Enhancement |
| | 636e535 | Add cov erity support in devicesettings-hal-emulator | |
| | 6f82971 | Enable xupnp for broadband | |
| | bd64b66 | Add support for cov erity | |
| | 907cbc5 | Add support for cov erity | |

| | | | | |
|--------------------------------------|---------|--|-------------|---------|
| | 6bee2fc | RDKCOM-867: Ref Platform test coverage improvement | | |
| | c7585b4 | Remove pinning of parodus in parodus2ccsp | Bug Fix | |
| meta-rdk-ext/ | 944b3ad | WKIT-1165: XRE key mapping | Enhancement | |
| | 4d008f7 | RDKALL-1278: Upgrade libfontconfig to 2.12.1 | | |
| | 20ef393 | XRE-13988: Initial support for Dolby Vision | | |
| | de2be37 | RDKB-21548 :Develop code to support Secondary XDNS server | | |
| | 9ff7371 | BCOM-3327 - [DASH] Support iframe trickmode for multi period assets. | | |
| | 3d658a6 | RDKCMF-8527 Upstream latest version of lxc-container-generator | | |
| | 8c8e5df | XRE-13799: Tracking playback of encrypted contents in WebApps | | |
| | c35eaef | RDKPI-214: Moving RPI RNE generic changes on stable2 branch | | |
| | 968b848 | RDK-23485: Log milestones related to DHCP | | |
| | 72c0155 | RDK-21755, RDK-23613: [RNE] SDK download from USB | | |
| | a64a818 | RDKALL-1627 : Security Vulnerability for glibc, zlib and libtasn1 | | |
| | d0fcc97 | RDKB-12488 RDKB does not support the option to override the debug.ini file | | Bug Fix |
| | 85fd858 | XMITD-503 : Confusing nopoll msg about mutex unlock not required | | |
| | 185ebbd | RDKALL-1332: Disable lighttpd symlink following | | |
| | 041bf1f | BLDK-679 Add removed headers in meta-rdk-ext dnsmasq patches | | |
| | 34c40e4 | RDKB-15078: Merge XDNS patches + add patched from meta-rdk-mesh | | |
| | 315c2ca | RDKCOM-912,REFPLTB-256: Unnecessary build dependency in lxc recipe | | |
| | 3a1072e | RDKB-21133: Add RDKB-Fix-BindReuse-Bug.patch on top of dibbler 1.0.1 | | |
| | dc00e7d | RDKB-267 : Fixes for timeouts and race conditions in ccsp message bus | | |
| | 28fd3b8 | BCOM-3348 : Web/Network process mini-dump fail | | |
| | 4da66bf | XRE-13975: Invalid Key codes are received for Color keys in Remote | | |
| | 94e1e1e | XF3-4781 : dnsmasq service file change | | |
| | 112e271 | BLDK-631 : meta-rdk-ext contains RDK-M proprietary licenses | | |
| | f1b5085 | XONE-19999: All video apps are coming up with black screen | | |
| rdk/components/generic/crashupload / | 9b3e044 | RDKB-22558 : Observing "too many arguments" error in uploadDumps.sh | Bug Fix | |

| | | | |
|--|----------|---|-------------|
| | d57d790 | RDKB-21996,ARRISXB6-9480 : Mac address is shown as 000000000000 | |
| rdk/components/generic/lxc-container-generator/ | f5d1f0c | RDKCMF-8527 Upstream latest version of lxc-container-generator | Enhancement |
| rdk/components/generic/rdk_logger/ | 56f93b2 | ST2-1914 and ST2-1301 : Porting RDK logger for speedtest on to non-atom chips | Enhancement |
| | 5da83a0 | RDKB-12488:RDKB overriding support in debug.ini | Enhancement |
| rdk/components/generic/rdm/ | e41da7c | Remove CEDM command logging from scripts | Bug Fix |
| rdk/components/generic/rfc/ | 9ef6138 | RDK-23405 : Default Device Configuration overridden by RFC | Enhancement |
| | 46ad0e0 | RDKALL-1335: Improve reporting for RFC feature enable | |
| | 144cde7 | RDKB-20875: Remove IDS Component(RFC) | Bug Fix |
| rdk/components/generic/xupnp/ | 49fb69c | RDK-23477: Log milestones related to xupnp | Enhancement |
| rdkb/components/generic/CcspLogAgent/ | 9bfa479 | RDKB-12488 RDKB does not support the option to override the debug.ini file | Enhancement |
| rdkb/components/generic/servicemanager/ | 64e95be | RDKB-12488 RDKB does not support the option to override the debug.ini file | Enhancement |
| rdkb/components/opensource/ccsp/CcspCMAgent/ | 855a01d | INTEL-361: Addition of CM HAL for DOCSIS 3.1 Extended Packet Support | Enhancement |
| | bfdca8f | RDKB-21305 :TR-181 FirmwareDownloadNow set issue | Bug Fix |
| | b3f9bd6 | RDKB-305: Issue with disabling/excluding CcspLogAgent from the firmware | |
| | 0ef8758 | INTEL-401 BootFileName buffer is 64Byte but RFC support 255 bytes | |
| rdkb/components/opensource/ccsp/CcspCommonLibrary/ | 6f04acf2 | RDKB-21186: log_journalmsg.service never goes to active state | Bug Fix |
| | 44749e34 | RDKB-21789: Rabid activation and selfheal sync | |
| | da548858 | RDKCOM-137 RDKBCMF-97: Fix 'Out-of-bounds read' in CcspCommonLibrary | |
| | a9e7e2c3 | RDKB-12488 RDKB does not support the option to override the debug.ini file | |
| | babdb115 | RDKB-308 Memory Leak in Ccsp-Common-Library Component | |
| | 550579cb | RDKB-267 : Fixes for timeouts and race conditions in ccsp message bus | |
| | 0754cbec | RDKCOM-895: RDKB-276: Fix for Memory leak in Cdm_GetParamGrp() | |
| | d336b13d | ARRISXB3-7771 , RDKB-20840 , RDKB-21210 : brlan0 is down | |
| | fa584249 | RDKALL-1304 : Use default work directory for parodus | |
| | | | |

| | | | |
|---|----------|--|-------------|
| | 6deaa52d | TCXB6-4886 : Waiting for gretap0 to be ready in logs and each time it is failing | |
| | 0837e760 | TCXB6-6211 : Observed CcspCMAgent crash due to DslhWmpdoMprGetVarRecord. | |
| rdkb/components/opensource/ccsp/CcspCr/ | 1f1b947 | RDKB-12488 RDKB does not support the option to override the debug.ini file | Bug Fix |
| rdkb/components/opensource/ccsp/CcspEPONAgent/ | a5c7122 | RDKCOM-136 RDKBCMF-96: Fix 'Out-of-bounds read' in CcspEPONAgent | Bug Fix |
| rdkb/components/opensource/ccsp/CcspEthAgent/ | 331ea31 | RDKB-12488 RDKB does not support the option to override the debug.ini file | Bug Fix |
| | 4eff3e7 | RDKB-305: Issue with disabling/excluding CcspLogAgent from the firmware | |
| rdkb/components/opensource/ccsp/CcspHomeSecurity/ | 4e82962 | RDKB-21340 :Move RDK Repo/Password on generic repository to a cpc repository | Enhancement |
| rdkb/components/opensource/ccsp/CcspLMLite/ | 098243d | RDKB-22057 : SetLED binary to set the LED behavior | Enhancement |
| | c6ecf5e | RDKB-302 - LMLite-In lm_cmd_thread_func accept system call is not using length param correctly | Bug Fix |
| | d591312 | RDKB-21105 : Telemetry for TS offline/online Status | |
| | 4c14925 | CISCOXB3-5108 :Observing App CcspLMLite crash. | |
| | 3471185 | RDKB-21180 : "No of Clients connected" displays the value as 0. | |
| | 692fa2c | RDKB-12488 RDKB does not support the option to override the debug.ini file | |
| | fe118a6 | RDKCOM-129 RDKBCMF-82 Fix 'Missing return statement' in CcspMisc | |
| rdkb/components/opensource/ccsp/CcspMoCA/ | c51df00 | RDKB-22302 : High CPU consumption due to usr/bin/CcspMoCA -subsys eRT | Bug Fix |
| | e15d41d | RDKB-12488 RDKB does not support the option to override the debug.ini file | |
| rdkb/components/opensource/ccsp/CcspMtaAgent/ | 0c6d5d0 | RDKB-21282,RDKB-20910: Implementation of TR181 and partner_defaults for MTA | Enhancement |
| | 82da43a | RDKB-12488 RDKB does not support the option to override the debug.ini file | Bug Fix |
| | 507f5e8 | INTEL-401 BootFileName buffer is 64Byte but RFC support 255 bytes | |
| | b6c58bb | RDKB-305: Issue with disabling/excluding CcspLogAgent from the firmware | |
| | bcc9cdd | RDKCOM-132 RDKBCMF-85 Fix 'Missing return statement' in CcspMtaAgent | |

| | | | | |
|--|---------|--|---------|-------------|
| rdkb/components/opensource/ccsp/C cspPandM/ | 5460329 | REFPLTB-289 REFPLTB-326: Reference Implementation (Broadband) of Liberty Containerization implementation on R-Pi | Feature | |
| | e320bdf | RDKB-20862, RDKB-21282 : Implement bootstrap functionality for TR69 Enablement. | Feature | |
| | ca05b5f | RDKB-20841,XAIS-1976: Add TR181 for Rabid On & Off. | | |
| | 5112502 | RDKBCMF-197: Data Model support for firewall feature like port forwarding/port triggering, DMZ etc for Multi-Lan | | |
| | 127f547 | REFPLTB-289: Reference Implementation (Broadband) of Liberty Containerization implementation on R-Pi | | |
| | b36f5aa | RDKB-21736,XAIS-2343: Support Rabid Tr181 in XB6. | | Enhancement |
| | d91db3b | RDKB-21318 :Implement TR-181 parameter to support secondary XDNS Servers | | |
| | 083621c | RDKALL-1675: RDKB changes for adding new RFC parameter | | |
| | 9be5a49 | RDKB-19591 : Implement TR-181 parameter to switch dhcp v6 client. | | |
| | 8a3a89e | RDKBCMF-220 : Use hardware mem functions for CI20 | | |
| | 429c456 | RDKBCMF-197: Data Model support for firewall feature like port forwarding/port triggering, DMZ etc for Multi-Lan cf8e38b | | |
| | b405982 | RDKB-20614, ARRISXB3-8960 :Route Camera Video Between XH WiFi and Private WiFi | | |
| | 67949a2 | RDKB-21026 : Partner Json version support. | | |
| | f1221cd | RDKB-15051 : Enabling data model for X_CISCO_COM_FileTransfer in BCI model | | |
| | 28f4fe1 | RDKB-21380: Get CM_MAC & FW_VER from platform HAL | | |
| | d2f3d68 | RDKB-22080, RDKB-21790 : Gateway LED SHALL blink white | Bug Fix | |
| | c3017e2 | RDKB-12488 RDKB does not support the option to override the debug.ini file | | |
| | a302219 | RDKBCMF-190: Performance impact on accelerated traffic during firewall restart on ipv6 renewal | | |
| | 27bdd29 | RDKB-305: Issue with disabling/excluding CcspLogAgent from the firmware | | |
| | 165cd95 | REFPLTB-295: [TDK]Not able to set any port value to Device.X_CISCO_COM_DeviceCont rol.HTTPPort | | |
| | | | | |

| | | | |
|---|---------|---|-------------|
| | 75763ca | REFPLTB-286: [TDK][WIFI][Emulator]Device.X_CO MCAST_COM_GRE.Interface.1.Stat us expects uint value unlike other platforms REFPLTB-287: [TDK][WIFI][Emulator]Device.X_CO MCAST-COM_GRE.Tunnel.1.Status expects uint value unlike other platforms | |
| | d0ffbce | RDKBCMF-221 : Fix factory reset issue for CI20 | |
| | 34801c8 | INTEL-362: Ethernet DataModel mapping is not correct for Ariss Xb6 and PUMA7 | |
| | cf8e38b | XF3-4869 :Remote Management IPv6 address missing in Advanced >Remote Management | |
| | 7623b64 | RDKCOM-138 RDKBCMF-98 Fix 'Out-of-bounds write' in CcspPandM | |
| | 450919f | RDKB-21682 : Observed "-sh: avahi-daemon: command not found" | |
| | a920710 | XF3-4624 : Remove cJSON_GetErrorPtr in CcspPandM | |
| | 98253fc | TCXB6-5823 CcspPandMSsp App crashing due to libc-2.19.so signatur e | |
| | 8be7f19 | RDKB-20875: Remove IDS Component(RFC) | |
| | fa07a20 | RDKB-20519 :DMZ v4 Host accepts IP which is not in DHCP range | |
| | 67e0d39 | TXB6VTN-94 : Footer link redirected incorrectly | |
| | d36c00e | XF3-4759 Remote Management | |
| rdkb/components/opensource/ccsp/C cspPsm/ | 5e1e3bd | RDKB-12488 RDKB does not support the option to override the debug.ini file | Bug Fix |
| | b9c11be | RDKB-22552: TXB6 devices on getting 10.0.0.1 as brlan0 instead of 192.168.0.1 | |
| | 523dd8d | RDKB-305: Issue with disabling/excluding CcspLogAgent from the firmware | |
| | 68fe6ab | RDKB-15015 : Device rebooted due to PSM crash. | |
| | 610a6f4 | RDKB-21155 CcspPsm Unapproved Cisco Copyrights | |
| | 93b50eb | RDKB-21687: Set default value of Device.WIFI.vAPStatsEnable to true | |
| rdkb/components/opensource/ccsp/C cspSnmpPa/ | 5a9af16 | RDKB-19970 : RDK-B MiB File | Enhancement |
| | bafe238 | RDKB-272: RDKB ccsp-snmp-pa agent leaks memory while running RDKB MIB | Bug Fix |
| | 3563c28 | RDKB-12488 RDKB does not support the option to override the debug.ini file | |
| | 65c858e | RDKB-310 - SelfHeal renaming and exposure of SelfHeal parameters over TR069 | |
| | f2ee089 | RDKB-300 SNMP - Memory Leak Fixes | |
| | | | |

| | | | |
|--|----------|---|-------------|
| | ca5559a | RDKB-300 SNMP - Memory Leak Fixes | |
| | d85cdd5 | RDKB-285: snmpset failing due to mismatch between ccsp-snmp-pa and Data Model | |
| | 5d359ba | RDKCOM-921: RDKB-294 SNMP - Possible invalid memory access due to ccsp_tabl... | |
| rdkb/components/opensource/ccsp/CcspTr069Pa/ | bccbbaa6 | RDKB-20862 : Implement bootstrap functionality for TR69 Enablement. | Feature |
| | 683c225 | RDKB-310 - SelfHeal renaming and exposure of SelfHeal parameters over TR069 | Bug Fix |
| | 3624f10 | RDKB-12488 RDKB does not support the option to override the debug.ini file | |
| | ce556d2 | RDKB-297 TR069 - Parameter Key char array without room for the null terminator | |
| | 97b3782 | RDKB-299 Device.WiFi.SSID.1010X.SSID will not restart radio2 when ACS sets more than 10 parameters | |
| | 472be8d | RDKB-305: Issue with disabling/excluding CcspLogAgent from the firmware | |
| | 7b2502e | RDKB-298 TR069 - Device.DeviceInfo.ProvisioningCode in Inform ParameterList didn't update after changes | |
| | 012c82f | RDKB-295: CcspTr069PaSsp crashes while trying to free invalid memory during GetParameterAttributes call | |
| | 4c73dfa | XF3-4624 : CcspTr069PaSsp process crashed in signature cJSON_GetErrorPtr | |
| | b3fa03f | RDKCOM-910: RDKB-293 - Memory leak in Ccsp-Tr069-Pa | |
| | 4ece78f | XF3-4826 : Observed syntax error log print | |
| rdkb/components/opensource/ccsp/CcspWifiAgent/ | a16bc51 | RDKB-20037: Telemetry marker for Tx Overflow | Enhancement |
| | 4c8cf3c | RDKB-21718 : Bootup changes for Mesh Vaps | |
| | 4d31361 | RDKB-21890: Handling duplicate entries in wifi monitor hash map | |
| | 39ec0a1 | ARRISXB3-8544 High ARM load average and devices are | |
| | d600dbe | ARRISXB3-8848 : Telemetry marker for TX OVERFLOW | |
| | cbbd51b | CISCOXB3-5101 , RDKB3939-468 : Peer_down reboot | |
| | b661247 | RDKB-12488 RDKB does not support the option to override the debug.ini file | Bug Fix |
| | ca90e81 | RDKB-22265 : VAP percentages are not reported in the expected format | |
| | e4ffc13 | RDKB-20952: Observing Memory Leak in CcspWifiSsp. | |

| | | | |
|--|---------|--|-------------|
| | 9cc6b84 | REFPLTB-284: [TDK][WIFI][Emulator]SSID enabling and disabling is not reflecting in SSID Status | |
| | c5a9027 | RDKBCMF-226 CcspWiFiAgent: SupportedStandards for radio is not showing correct value | |
| | dbc8efd | .RDKB-22503 : Modify Tunnel object in hotspot component | |
| | c1d6857 | RDKB-22663,CISCOXB3-5378:pope n failed | |
| | 4b8e0fc | CISCOXB3-5273: [Field][Data-Analysis] Increase in wifiagent process crash with | |
| | 0cda292 | RDKB-16077: [Field][XB3][Data_Analysis] Correct wifihealth.txt as per code. | |
| | 59c018b | RDKB-21643: Handling process disconnect inside de authentication Call Back. | |
| | d09552c | RDKB-17143: Create telemetry markers for WiFi password Failure. | |
| | 82f7ced | RDKB-20952: Observing Memory Leak in CcspWifiSsp. | |
| | c2cda2e | RDKB-21823,RDKB3939-926 2G/5G_PS_Clients_split in PowerSave queue has increased | |
| | 4ee50ee | RDKB-21301 : | |
| | d4e62a3 | RDKB-21687: Set default value of Device.WiFi.vAPStatsEnable to true | |
| | e9ee06c | RDKB-21441, RDKB-20517 [3.4p1s2]Few WiFi markers are missing in wifihealth.txt | |
| | 8c51044 | XF3-4414 : Additional logs added when Wi-Fi interfaces channel set to manual | |
| | 2513c38 | TCXB6-6459: Wifi channel Split is Not reporitng in Wifihealth.txt. | |
| rdkb/components/opensource/ccsp/CcspXDNS/ | 9f5b962 | RDKB-21318 :Implement TR-181 parameter to support secondary XDNS Servers | Enhancement |
| | 28164e0 | RDKB-22149 :CcspXdnsSsp crash while trying to delete entry from table | Bug Fix |
| rdkb/components/opensource/ccsp/GwProvApp/ | 0aef077 | REFPLTB-289: Reference Implementation (Broadband) of Liberty Containerization implementation on R-Pi | Enhancement |
| | 796e845 | RDKCMF-8288: DS-Lite - Support IPv4 on LAN side devices when eRrouter is configured for IPV6 only | |
| | 2b10d91 | RDKB-20453: Adding compile time Macros to Multilan | |
| | 7177773 | RDKCOM-904 RDKBCMF-42 : Remove Docsis Dependencies from GwProvApp for Rasp... | |
| | 36b8886 | RDKBCMF-180: LAN is not starting for PUMA7 platform with rdkb-20180426 release | Bug Fix |
| | 9ff50e1 | ARRISXB6-8594: 0014-Snmp-fix-for-esafeErouterOper Mode-oid.patch | |

| | | | |
|---|----------|--|-------------|
| | 485489a | RDKCOM-923 RPi build failure in Ccsp-GwProvApp | |
| | 72a6163 | RDKBCMF-180: LAN is not starting for PUMA7 platform with rdkb-20180426 release | |
| | fb62d75 | RDKB-15121: Unknown icons in GwProvApp | |
| | e9418c6 | TCXB6-4886 : Waiting for gretap0 to be ready in logs and each time it is failing | |
| rdkb/components/opensource/ccsp/GwProvApp-EthWan/ | 55691c9 | RDKB-22146: ETHWAN mode if no connectivity, LED should blink yellow | Enhancement |
| | 2d0cceef | TCXB6-6365: MTA voice HAL implementation | |
| | 6a08f70 | RDKB-22624: [ETHWAN] Rev SSH is failing on stable build | Bug Fix |
| | 36a3780 | RDKB-21951: [ETHWAN] Rev SSH stopped working in ETHWAN mode | |
| | ce03f3f | RDKB-21410: EWAN Invalid Source MAC Blocks Internet Access | |
| rdkb/components/opensource/ccsp/ MeshAgent/ | 06c228f | RDKB-21719 : Removal of wifi reset | Bug Fix |
| | cc4600f | RDKB-21986 : Customer sensitive data logging removal | |
| rdkb/components/opensource/ccsp/T estAndDiagnostic/ | 887ac02 | RDKB-21737,XAIS-2344: Add Selfhealing for Rabid in XB6. | Feature |
| | a234c69 | RDKB-21416,XAIS-2001: Rabid self heal implementation. | |
| | bdf9f29 | RDKB-20261 RDKB-21729: Add newer platforms to script | Enhancement |
| | ef6cac6 | RDKB-21216 : self heal to restart Parodus stuck connecting | |
| | b99d727 | CISCOXB3-5101 , RDKB3939-468 : Peer_down reboot | |
| | d71fd9c | RDKB-21661,RDKB-21675 : required additional logs to detect crashes | |
| | 4ed6113 | RDKB-312 DownloadDiagnostics were not working for binary files | Bug Fix |
| | d3d99e1 | RDKB-310 - SelfHeal renaming and exposure of SelfHeal parameters over TR069 | |
| | 1527d4c | XF3-4946 : Killing Zombie dnsmasq and restarting it | |
| | 56f8a82 | XF3-4910 : No network connection in SSID's and Ethernet | |
| | d1da4be | RDKB-21101 : Higher Boot timers | |
| | 360c71a | RDKB-18447 : Observed Mac of Atom eth0 as one of the connected client. | |
| | 6bd6f0c | ARRISXB3-8691 : continuous DbusSend error and failed to sync with Imlite | |
| | 1276c7c | RDKB-22628: Observed "sh: argument expected" entries in SelfHeal Logs | |
| | 0ec68d1 | RDKB-21754,CISCOXB3-5249 , CISCOXB3-5154 : CR_Crash Selfheal Improvement | |

| | | | |
|---|--|--|-------------|
| | 25835d4 | RDKB-19566 : Change self Heal script based on syscfg flag | |
| rdkb/components/opensource/ccsp/Utopia/ | 354fdb0 | RDKB-20862, RDKB-21282,RDKB-20910 : Implement bootstrap functionality | Enhancement |
| | 26ed554 | RDKB-19443,RDKB-19444 : Switch logic for DHCPv6 client | |
| | 03eafdf | RDKBCMF-213: Add IPv6 General Purpose rules to the firewall using sysevents | |
| | 1877fd9 | REFPLTB-171: Client devices blocked using MACFiltering is able to connect to gateway on rpi | |
| | 4f95a8a | RDKALL-1299: Securing syscfg.db in /opt/secure/data/ folder in CBR. | |
| | 94ab102 | INTEL-399 bridge mode is broken on rdkb-2019q1 tag | |
| | fcda947 | TCCBR-3783 :Invalid WAN IP error alert seen when set True Static IP via mso page | |
| | 67eed11 | RDKBCMF-185: set connection tracking max to 16k entries for puma7 | |
| | 03e754a | RDKB-22624: [ETHWAN] Rev SSH is failing on stable build | |
| | f71af07 | TCXB6-6646 : Error in "/etc/utopia/service.d/lan_handler.sh" | |
| | db2a1f2 | RDKB-22008: Remove X_RDKCENTRAL-COM_LastReconnectReason | |
| | dec1381 | RDKBCMF-190: Performance impact on accelerated traffic during firewall restart on ipv6 renewal | |
| | b230e56 | RDKBCMF-193: IPv6 Packets from non-routable CPE addresses are forwarded to WAN | |
| 3b5baf2 | Logs not being rotated because of BOX_TYPE match | | |
| b184be8 | RDKBCMF-154: RDKB fixes from Intel part 2 | | |
| 710f7f2 | RDKBCMF-195: In pseudo bridge mode, brlan0 should not have IPv6 global address | | |
| 40ecc25 | RDKBCMF-194: Blocked devices are not blocked properly for IPv6 | | |
| 1ecbdc2 | RDKB-22105: Remove system_defaults_webpa.patch and add to system_defaults_bci | | |
| 1105bcd | RDKB-15855: Buffer overflow vulnerabilities found in IGD code | | |
| 99d64e7 | XF3-4624 : Remove cJSON_GetErrorPtr in Utopia | | |
| 1daa94f | INTEL-383: Removing iptable rules for I2sd0.500 and I2sd0.4093 in PUMA7 | | |
| e7a4c52 | RDKCOM-855: Removing iptable rules for I2sd0.500 and I2sd0.4093 in PUMA7 | | |
| dfb10aa | RDKB-15122 : Removing unknown icons | | |

| | | | |
|---|---------|---|-------------|
| | cd346ed | RDKB-21165 : Redesign parsing of partners_default.json during bootup | |
| | de989ae | ARRISXB3-8684 : Observed "uologd: not found" error message in Armconsole logs | |
| | 65b946b | ARRISXB3-8656 : Observing "/bin/sh: deluser: not found" | |
| | e56ca2b | RDKCOM-933: fix for Compilation error during Multilan feature testing | |
| | ba7fdbc | RDKB-20875: Remove IDS Component(defaults) | |
| | 82561ab | CISCOXB3-5040 : Observed CXB3 3.3p10s1 reporting crashes | |
| | 04e7371 | RDKB-21731: Partner ID is changed to Comcast, COX devices are showing Xfinity | |
| rdkb/components/opensource/ccsp/hal/ | 6a52ef4 | . INTEL-361: Addition of CM HAL for DOCSIS 3.1 Extended Packet Support | Enhancement |
| | 44329ec | REFPLTB-290: [TDK][WIFI][EMULATOR] Unable to set the value PSK to 64 characters(HEX value) using wifi_setApSecurityPreSharedKey() api for both 2.4GHz and 5GHz. | Bug Fix |
| rdkb/components/opensource/ccsp/halinterface/ | 202df29 | RDKB-20978: Define new Status LED HAL | Enhancement |
| | dd5e3b6 | RDKB-20907: Create hal definition for voice provision mode | |
| | 0c1ee33 | RDKB-20037: Telemetry marker for Tx Overflow | |
| | 7c24d1c | INTEL-361: Addition of CM HAL for DOCSIS 3.1 Extended Packet Support | |
| | 3f9ecf8 | RDKB-20332 : wifi_BeaconReport_t member type modification to meet spec | Bug Fix |
| rdkb/components/opensource/ccsp/hsynt/ | 25afa37 | RDKALL-1675: RDKB changes for use URL from RFC | Enhancement |
| | 3edf1cb | RDKB-22538,CISCOXB3-5161: Fix for RDKALL-971 | Bug Fix |
| | eedf28d | RDKB-22449 : Observed "tar: write error: Broken pipe" in ArmConsole Logs | |
| | 91acce9 | RDKB-21821: RebootPendingNotification set failure in Consolelog during reboot | |
| | 4dfe0e3 | RDKB-22448 : Observed "cat: write error: Broken pipe" in Arm Console Logs | |
| | 24af9a4 | RDKB-21394:Curl request logged should contain encrypted | |
| | 8597ea5 | RDKB-21280 : Correct errors in synchronization logic | |
| | 85ab11a | RDKB-21381 : Fix for avoiding warnings | |
| | b45f76f | RDKB-21101 : Higher Boot timers | |
| | 5b9399e | RDKB-20875: Remove Samhain upload2splunk.sh | |

| | | | |
|--|--|--|-------------|
| | c2be664 | RDKB-21351 : Logs are not flushing even after upload | |
| rdkb/components/opensource/ccsp/webui/ | cbf0ae3 | RDKCOM-685 RDKCMF-6316 : To add README.md and doxygen comments in ccsp Web... | enhancement |
| | 3340a73 | RDKB-269 RDKB webUI: Radio/SSID indexes for 2.4G and 5G radios are hard-coded in php files | |
| | 7c5a596 | RDKB-269 RDKB webUI: Radio/SSID indexes for 2.4G and 5G radios are hard-coded in php files | |
| | 11ba05b | RDKB-269 RDKB webUI: Radio/SSID indexes for 2.4G and 5G radios are hard-coded in php files | |
| | 6358b39 | RDKB-15685: webui contains jquery code of unclear origin and license . | |
| | a253dc0 | RDKB-18052: Use OAUTH to replace POTD | |
| | 5806dd1 | RDKB-20278: Typo in Alert message - Port Forwarding. | Bug Fix |
| | 67a22e4 | RDKB-17017:Mismatch in pop up timers for reset wifi module and router in UI. | |
| | b5c7b04 | RDKB-21075 : | |
| | 2b9103c | RDKB-22092,RDKB-22091:Ethwan changes. | |
| | 06e04b0 | RDKB-21591:DDNS page,default values are stored when entering longer strings. | |
| | b27ba69 | RDKB-15688 :webui contain icons of unknown origin. | |
| | 9bbec7b | RDKBCMF-199: Disable SSL support from webgui | |
| | 97d2ee7 | Fix hardware info mem total | |
| | 10c1990 | RDKCMF-8515: WebGUI was not accessible sometime | |
| | 6cb5b18 | RDKB-264: Xfinity UI admin page "Access denied" while connecting by IPV6 address | |
| e10a61b | RDKB-19592 TCXB6-6669: Battery life is showing as 8 hrs in GUI | | |
| a3cc96a | RDKB-20846:Duplicate entries of same device is listed under Blocked devices. | | |
| 9926567 | RDKB-19298: Changing security mode to open should not prompt for password. | | |
| f468739 | RDKB-20983:Host Name Validation fails for Dynamic DNS. | | |
| a299c16 | RDKB-19292: Attack vector in dynamic_dns_edit.php | | |
| ef8f4e0 | XF3-4723: Band Steering in XF3. | | |
| rdkb/components/opensource/ccsp/xb3/ | a915ac2 | RDKB-21519 : rdkbemu_xb3 contains unapproved Cisco copyrights | Bug Fix |
| rdkb/docs/ | f5bdf25 | Add changelog for rdkb-20190530 iteration | NA |

| | | | |
|-------------|---|--|-------------|
| tools/tdk/ | 9db4f46c | TDKB-720 : Reference platform test coverage improvement | Feature |
| | cb748645 | TDKB-698 : Modify WEBUI framework | Enhancement |
| | 175b1783 | RDKTT-1619: Ref Platform test coverage improvement | |
| | 3b9f5e9a | RDKTT-1427 : Interface change for script DS_EnableHDCP_InvalidKeySize_132 | |
| | dcabbca8 | RDKTT-1590: TDK M64 release | |
| | 4eba7035 | RDKTT-1608 : WEBPA Coverage Improvement | |
| | 14bb7edf | RDKTT-1590 : Updated TDK agent version | |
| | ae12cb35 | RDKTT-1596 : Option to download all the test case documents together as zip | |
| | 4eb1f1ef | RDKTT-1596 : Option to download all the test case documents together as zip | |
| | 35b6111e | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | 134ed2f3 | TDKB-698 : Modify WEBUI scripts | |
| | 010ac724 | RDKTT-1587: TDK M63 release | |
| | 63c1116b | TDKB-655 : E2E coverage improvement | |
| | ce0af0d7 | TDKB-655 : E2E coverage improvement | |
| | 816e951b | RDKTT-1493 : Updated Test Manager version | |
| | 8565f80e | RDKTT-1493 : Updated TDK agent version | |
| | 3a2f8c30 | TDKB-694 : E2E SSH script issue | |
| | 2d2275b9 | RDKTT-1009: TR069 DeviceIPInterfaceNumofEntries_32 script | |
| | 951dd068 | TDKB-598 : webpa pre-requisite modification | |
| | aee7fac8 | RDKTT-1581: IARM_Bus_Call - power manager is returning invalid state | |
| a5582957 | TDKB-635 : Modify E2E scripts for Webpa | | |
| | | | |
| tools/tdkb/ | 9042cb0 | TDKB-743 : M65 Coverage improvement | Enhancement |
| | ccd85a4 | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | daa7844 | TDKB-538: Script Modification for handling Factory Reset | |
| | 2949ca0 | TDKB-565: Script modification for SNMP_PA module | |
| | 78cbd4d | TDKB-417 : WIFIHAI script modification | |
| | a91a6ff | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | | | |

| | | | |
|---|---------|---|-------------|
| | 82f1fc6 | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | 28814f8 | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | ddca24d | TDKB-615: Script Modification for platform hal | |
| | 28fc6bb | TDKB-672 : WIFIHAL coverage improvement-M64 | |
| | 3177c18 | TDKB-672 : WIFIHAL coverage improvement-M64 | |
| | 61bd666 | TDKB-518:WiFi Hal: script Modification M60 Release | |
| | eab0ed9 | TDKB-589: Script modification for WIFIHAL | |
| | c75cc4f | TDKB-672 : WIFIHAL coverage improvement-M64 | |
| | 4d4bebb | TDKB-672 : WIFIHAL coverage improvement-M64 | |
| | 91a687d | TDKB-672 : WIFIHAL coverage improvement-M64 | |
| | 29c99e0 | TDKB-672 : WIFIHAL coverage improvement-M64 | |
| | fcfc0b | TDKB-703 : Modify WIFIHAL scripts | Bug Fix |
| | 480880c | TDK-1313 : RDKB EMU TS_WIFIHAL GetSSIDMACAddress Failures | |
| | 87eb233 | TDKB-646 : WIFIHAL | |
| | 547a99a | TDKB-478:WiFi Hal: setRadioMCS scripts | |
| | be7b8a1 | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | ba97dc5 | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | 1cedcba | TDKB-709 : Modify TDK_version.txt | |
| | 946a731 | TDKB-604 : WiFi HAL script correction | |
| | 4a7940c | TDKB-709 : Test and Diagnostics Coverage improvement | |
| | 96cea4f | TDKB-709 : Test and Diagnostics Coverage improvement | |
| tools/tdkb/platform/raspberrypi/ | d892cf1 | TDKB-709 : Test and Diagnostics Coverage improvement | Enhancement |
| | a9b67fd | TDK-1226 : tdk_platform.properties modification | Bug fix |
| | 46af823 | TDK-891: WEBPA pre-requisite | |
| project tools/tdkb/platform/rdkbemulator/ | 06e3893 | TDKB-709 : Test and Diagnostics Coverage improvement | Enhancement |
| | c6c8617 | RDKCOM-927: TDK-1226 : tdk_platform.properties modification | |

Bug Fix