

# RDK-V W47 Sprint 20 Nov - 01 Dec

Team Capacity - 80

Engineer Name	Total sprint velocity in days (10 days) [A]	Holiday (1 day) [E]	Planned Leave [B]	Unplanned Leaves [F]	Default Velocity in days [A-B-E]	Backup Velocity in days for adhoc requests(1 days), If no adhoc requests this 1 days to be spent for a new Jira [C]	Scrum related activities(only for Scrum Master), Default 5 days and 1 day for individual contributor for their scrum activities [D]	Net capacity in days [A-B-E-D]
Sowmya	10	0	3		7	0	3	4
Rosna	10	0	2		8	0	4	4
Philip	10	0	0		10	1	1	9
Dinesh	10	0	0		10	1	1	9
Venkat	10	0	1		9	1	1	8
Balaji	10	0	1	1	9	1	1	8
Heam	10	0	6	4	4	1	0	4
Rajapriya	10	0	5		5	1	0	5
Rathi	10	0	9		1	0	0	1
Fryderyk	10	0	10		0	0	0	0
Shilpa	10	0	0	1	10	1	1	8
Harshini*	10	0	0		10	1	1	5
Naveen*	10	0	0		10	1	1	5
Pragada*	10	0	0	0	10	1	1	5
Sathish*	10	0	0	1	10	1	1	5
Total Team Velocity	150	0	37	7	113	11	16	80

\*- Freshers are marked \* against their name. Their bandwidth is calculated as 50%

Completed Story points - 35

Sprint Planning Bug Tickets/User Stories :

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status
Sowmya	BCM72180-262	DAC for YouTube Phase 1					1	BCM is not ready to merge the code.	Awaiting 3rd party
	SGMM393-968	RDKServices: [Intermittent] System plugin is not activating immediately after reboot	Y			2h			resolved
	BCM72180-800	Not Getting Video Player Ended Event for MVS EOS tests	Y			2	2		In Progress
	BCM72180-711	"onSystemPowerStateChanged" event is not getting triggered for ON state	Y					Followup	NA
	BCM72180-620	[PVS] Time taken for 'Destroy and Launch' is not within the expected range	Y			0.5	0.5		In Progress
	<a href="#">SGMM393-965</a>	Back button is not working during video playback in Youtube					0.5	Minor	Ready for Testing
Rosna	BCM72180-838	Enable syslog-ng in BCM platform		Y		1		Minor/ UnderReview	In Progress
	RDKVREFPLT-263	[SGMM393-821] Validation of webkit 2.38 on rdk-next		Y		3		Need to raise CL to BCM layer	In Progress
	RDKVREFPLT-577	[SGMM393-821] Validation of webkit 2.38 on rdk6-main		Y		1			InProgress
	BCM72180-845	Webpa API call is not responding	Y			0.5			Resolved
	BCM72180-849	Video playback is not working through gst-launch with playbin3 on wpe-2.38 build	Y			0.5			InProgress

[illegible]

	SGMM393-935	Blank screen is observed on trying to set screen resolution  using org.rdk.RDKShell.1.setScreenResolution method			1	1.5		In Progress
	BCM72180-619	[PVS] Time taken for 'Suspend and Resume' is not within the expected range			1	2		In Progress
	BCM72180-675	[FCA]: Localization.setTimeZone is returning error			1	1		Ready for Testing
	SGMM393-835	[FCA]: Localization.setTimeZone is returning error			0	1		Ready for Testing
	BCM72180-672	[FCA]: Default value is not available for Localization apis			1	1		Ready for Testing
	SGMM393-948	HLS playback with AAMP as source failing since nightly/  20231018-dunfell			0	2		In Progress
Naveen*	SGMM393-508	RDKService: 'ResidentApp MoveToFront' logs are not present in wpeframework.logs			1	3	Minor	Ready for Testing
	BCM72180-621	[PVS] Time taken for launch UI is not within the expected range			1	3	Major	In Progress
	<a href="#">DELIA-63780</a>	[RDK6]: Yocto Version not matching with specified versions			2			NA
	<a href="#">SGMM393-133</a>	The time taken for launching Main UI from another window  is not within the expected limit			0	1	Minor	Closed
	<a href="#">BCM72180-661</a>	Observing a blank screen during playback of featured VOD  content after  wpe-webkit 2.38 upgrade.			0	2	Minor	In Progress
Pragada*	BCM72180-671	[FCA]: Authentication.token type distributor is returning not supported			1	2	Major	Ready for Testing
	BCM72180-673	[FCA]: Parameters.Initialization throwing "Internal failure:  NotFound" error			1	2	Major	Ready for Testing
	BCM72180-708	RDKService: The trip time is higher than threshold time			2	0.5	Minor	Ready for Testing
	BCM72180-654	Time Zone API is returning false response			1	0.5	Minor	Ready for Testing
	<a href="#">BCM72180-685</a>	[TDK][BluetoothHal]Pairing to device is not persisted after reboot			0	1		Ready for Testing
	<a href="#">BCM72180-625</a>	[PVS] Time taken for  'WebKitBrowser_TimeTo_ActivateDeactivate' is not within the expected range			0	2		In Progress
	<a href="#">SGMM393-922</a>	Box is rebooting when setting power modes (Deepsleep) for alternate tries			0	1		In Progress
Sathish*	SGMM393-967	[External BT Audio Streaming]Audio not heard through Bluetooth sound bar after power cycle of Sound bar			1	2h		Ready for Testing
	SGMM393-778	Playback latency is larger than expected			3	0		NA
	SGMM393-970	Sagemcom build is failing in applying patch  restart_wifi_after_deepsleep.patch			1	2		In Progress
	SGMM393-930	Deep sleep mode showed issues			0	2		In Progress
	SGMM393-229	setPowerState is returning false when the power state is set to ON after standby and getPowerState is returning UNKNOWN			0	1		In Progress
	BCM72180-711	onSystemPowerStateChanged" event is not getting triggered for ON state			0	2		In Progress
	SGMM393-181	onSystemPowerStateChanged" event is not getting triggered for ON state			0	1		In Progress

Poland Team : NA

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status

Bug Triage:

Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Status