RDK-V W43 Sprint 23 Oct - 03 Nov

Team Capacity - 89SPs

Completed SPs -

Engineer Name	Total sprint velocity in days (10 days) [A]	Holiday (1 day) [E]	Planned Leave [B]	Unplanned Leaves [F]	Default Velocity in days [A-B-E]	Backup Velocity in days for adhoc requests(1 days), If no adhoc requests this 1 days to be spent for a new Jira [C]	Scrum related activities(only for Scrum Master), Default 5 days and 1 day for individual contributor for their scrum activities [D]	Net capacity in days [A-B-E-D]
Sowmya	10	1	2		7	0	3	4
Rosna	10	1	0		9	0	4	5
Philip	10	1	0		9	1	1	8
Vijith	10	1	0		9	1	1	8
Venkat	10	1	2		7	1	1	6
Balaji	10	1	1		8	1	1	7
Heam	10	1	0		9	1	1	8
Rajapriya	10	1	0		9	1	1	8
Shilpa	10	1	0		9	0	1	8
Rathi	10	1	2		7	1	1	8
Fryderyk	10	1	0	1	8	1	1	9
Arthur	10	0	0		10	1	1	9
Total Team Velocity	120	10	7		104	9	17	87

Tickets	Resolved/Closed/Ready for Testing	In Progress	Awaiting for 3rd party
	58 - SGMM/BCM 13- RDKVREFPLTV	22	6

Sprint Planning Bug Tickets/User Stories :

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status
Sowmya	SGMM393-807/ RDKVREFPLT-195	Launch/kill htmlapp		Y		1	1	CL failing in python3 Build machine	In Progress
	SGMM393-808/ RDKVREFPLT-196	launch/kill lightning app				1	1	CL failing in python3 Build machine	In Progress
	RDK6MAIN-85	DAC security (signing/encryption) support in RDK6							NA
	BCM72180-753/ RDKVREFPLT-380	DAC Feature is not working							Resolved
	BCM72180-262/ RDKVREFPLT-424	DAC for YouTube Phase 1					2	CL failing in python3 Build machine	In Progress
	RDKVREFPLT-425/ SGMM393-925	[SGMM393-925]Generalization of DAC Phase1 changes							NA
	SGMM393-641/ RDKVREFPLT-316	Failed to launch Cobalt in container mode						Dep on SGMM393-339	FROZEN

Assignee	Ticket	Summary					Comments	Status
	BCM72180-789/ RDKVREFPLT-426	Encrypted content is not playing back with DAC Ph1 YT launch						NA
	BCM72180-686/ RDKVREFPLT-500	Dobbytool List returns no containers after launching the application in container mode					CL failing in python3 Build machine	In Progress
	SGMM393-828	HDMI Audio is not playing in one Sagemcom box					Issue is not seen by us. Reporter should revalidate	In Progress
	BCM72180-812/ SGMM393-961	Apps Screen : ASMR Cloud app-store functionality is not working			0	1		Ready for Testing
	RDKVREFPLT-508	Bug triage and analysis of W43'23 sprint				1		Closed
Rosna	SGMM393-512 /RDKVREFPLT-374	[FCS][TDK]HEVC not properly playing at 3x and 4x playback rates						Resolved
	BCM72180-709/ RDKVREFPLT-499	RDKServices: Some of the temperature related APIs are not returning proper response in System plugin	Y	Y	0.5	0.5		Resolved
	BCM72180-381 /RDKVREFPLT-497	Some device info related parameters are not returning expected values	Y		1	1		Resolved
	SGMM393-624/ RDKVREFPLT-322	tr181 parameter not showing any response for Sagemcom device	Y		1	1		Resolved
	SGMM393-371 /BCM72180-716	RDKServices: org.rdk.DisplaySettings.1. getVideoFormat returned current Video format is returned as NONE			0.5		Need Comcast HAL implementation in dsVideo	Awaiting 3rd party
	SGMM393-945/B CM72180-803	[TDK][HdmicecHal]HdmiCecOpen call is failing			0.5		Resolved as TDK setup issue Both CEC1 nd CEC2 cant be enabled at same time	Resolved
	SGMM393-497 /RDKVREFPLT-498	In Automatics [TC-STB-WEBPA-011], For tr69 or tr181 commands not receiving any response from the device	Y		0.5	0.5		Resolved
Philip	BCM72180-696/ RDKVREFPLT-433	RDKServices: "org.rdk.FrameRate.2.getFrmMode" and "org.rdk.FrameRate.2.getDisplayFrameRate" APIs are not returning expected results			2	2	SOC implementation needed	Awaiting 3rd Party
	BCM72180-797/ RDKVREFPLT-504	RDKServices: org.rdk.Xcast.1.getProtocolVersion is not returning proper protocol version			2	2		Ready for Testing
	BCM72180-776 / RDKVREFPLT-383	[RVS] Some of the plugins with autostart as true are not activated after reboot			2	2		Resolved
	BCM72180-802/ RDKVREFPLT-506	[TDK][FCS]Waymetric application is missing			3	3		Awaiting 3rd Party
Vijith	RDKVREFPLT-525	[BCM/SGM] Porting rdk-next changes to rdk6-main - Phase6 (23Oct2023 - 3Nov2023)			7	6d 1h		In Progress
Balaji	BCM72180-697/ RDKVREFPLT-320	RDKServices: org.rdk.Wifi.1.getCurrentState API is not returning the wifi states properly						Awaiting third party
	SGMM393-847/ RDKVREFPLT-321	RDKServices: org.rdk.Wifi.1.getCurrentState API is not returning the wifi states properly						Awaiting third party
	SGMM393-539/ R DKVREFPLT-397	Unable to populate SDK tool chain						deferred for rdk6 release
	SGMM393-948/ RDKVREFPLT-509	HLS playback with AAMP as source failing since nightly /20231018-dunfell				1d	issue not observed in rc3 , worked after rc4	In Progress
	BCM72180-803 / RDKVREFPLT-514	[TDK][HdmicecHal]HdmiCecOpen call is failing				0.5d		Ready for testing
	SGMM393-945/ RDKVREFPLT-492	[TDK][HdmicecHal]HdmiCecOpen call is failing				0.5d		Ready for testing
	SGMM393-872/ RDKVREFPLT-512	RDKServices: Unable to enable and disable the wifi interface.				1.5d		Resolved

Owner	ID	Description					Notes	Status
	SGMM393-871/ RDKVREFPLT-510	RDKService: Error in getting the SSID details from "org.rdk.Wifi.1.getConnectedSSID"				1d		Ready for testing
	BCM72180-748/ RDKVREFPLT-400	DRM streams are not playing				1.5d		Inprogress
	BCM72180-741	Video playback is not happening properly for seek and fast forward operations				1d		Inprogress
Heam	BCM72180-766 / RDKVREFPLT-476	Back button Keypress didn't work from Tatlow RDK Voice remote	Y			1		Resolved
	BCM72180-765 /SGMM393-910/ RDKVREFPLT-389	After reboot, Alexa login is not persisted.	Y			1		Resolved
	SGMM393-940/ RDKVREFPLT-477	Power Key is not working in Tatlow RDK universal remote in Sagemcom device.	Y			1		Resolved
	SGMM393-937 /RDKVREFPLT-503	Unable to control volume using Tatlow RDK universal remote control	Y			1		Resolved
	BCM72180-381	Some device info related parameters are not returning expected values	Y			2	tested and raised cl for product class	Resolved
	SGMM393-915	Play /Pause voice commands does not act immediately and sometimes didn't respond too.	Y			1		Resolved
	BCM72180-685	[TDK][BluetoothHal]Pairing to device is not persisted after reboot	Y			1	Waiting for TDK team to test and close.	In Progress
Venkat	BCM72180-483/ RDKVREFPLT-326	RDK Services: DeviceIdentification plugin is not enabled in the device			3			Resolved
	BCM72180-716	RDKServices: org.rdk.DisplaySettings.1.getVideoFormat returned current Video format is returned as NONE			1		Need to implement Api dsGetVideoEOTF_t by soc broadcom team.	Awaiting Thirdparty
	BCM72180-670 RDKVREFPLT-212	[TDK][WifiHal]Radio Operating Channel Bandwidth is empty for 2.4GHz SSID			1			Resolved
	SGMM393-782 RDKVREFPLT-212	[TDK][WifiHal]Radio Operating Channel Bandwidth is empty for 2.4GHz SSID			1			Resolved
Rajapriya	RDKVREFPLT-232	[SGMM393-789] Speed change event observed for invalid set rate			-		Resolved already as part of SPRINT W41.	It is fixed on TDK side.
	RDKVREFPLT-418	[BCM72180-755] Speed change event observed for invalid set rate			-		Resolved already as part of SPRINT W41.	It is fixed on TDK side.
	RDKVREFPLT-339	[BCM/SGM] Porting of rdk-next changes to rdk6-main W39 - Phase4 (22Sep2023 - 07Oct2023)			3d		Completed	-
	RDKVREFPLT-419	[SGMM393-905] Apparmor Profiles DAC Override Capability Issue			2h		Resolved	Escalated to Broadcom and they fixed the issue.
	RDKVREFPLT-420	[BCM72180-774] Apparmor Profiles DAC Override Capability Issue			6h		Resolved	Escalated to Broadcom and they fixed the issue
	RDKVREFPLT-421	[BCM/SGM] Porting of rdk-next changes to rdk6-main W41 - Phase5 (09Oct'23 - 20Oct'23)			2.25d		Completed	-
	RDKVREFPLT-443	RTD131X-934, SGMM393-824:[TDK][FCS]Essos Direct EGL exit is causing crash.			-		Resolved already as part of SPRINT W41.	-

	RDKVREFPLT-488	[BCM72180-796] Broadcom hybrid DVB build is broken in nightly builds				0.5d		Resolved	Simon has made changes to disable libmediaplayer.
	RDKVREFPLT-496	[BCM/SGM] Porting of rdk-next changes to rdk6-main W43 - Phase6 (23Oct'23 - 03Nov'23)				3d		Completed	-
Rathi	RDKVREFPLT-422 SGMM393-924	[SGMM393-924] webp Image file not displayed in Webkitbrowser				1d	1d		Closed
	RDKVREFPLT-423 SGMM393-920	[SGMM393-920] Expecting 'No change response' (success code 304) in the /opt/logs/rfcscript.log for the last request made to xconf after reboot. Actual response : 200				1d	1d		Closed
	SGMM393-548 RDKVREFPLT-122	RDKService: eventInterfaceIPAddressStatusChanged is not triggered in the netsrvmgr logs				0h	0h		Inprogress
	SGMM393-926 RDKVREFPLT-450	MPEG and MPEG-TSstreams failed to play				0d	0d		Ready For Testing
	BCM72180-785 RDKVREFPLT-466	MPEG,MPEG-TS and AC3 streams failed to play				1d	1d		Ready For Testing
	SGMM393-945 BCM72180-803 RDKVREFPLT-492	[TDK][HdmicecHal]HdmiCecOpen call is failing				2d	2d		Ready For Testing
	SGMM393-830 RDKVREFPLT-336	After setting Power state to 'LIGHT_SLEEP', Box turn ON automatically with Power state to 'ON'				0d	0d		Ready For Testing
	SGMM393-935 RDKVREFPLT-467	Blank screen is observed on trying to set screen resolution using org.rdk.RDKShell.1. setScreenResolution method				1d	1d		NA
	BCM72180-800 RDKVREFPLT-517	Not Getting Video Player Ended Event for MVS EOS tests				2d	1d		Inprogress
Shilpa	BCM72180-736	Unable to get the audio in BCM reference devices of PIF team					0.5d		Resolved
	RDKVREFPLT-511	M10-W43 Bug Triage & Sanity Validation					4d		Closed
	RDKVREFPLT-513	M10-W43 Validation Support For DEV Team & UI Validation on 3.15.18					2.5d		Closed
	SGMM393-181, SGMM393-937	Validation of power modes, Validation of Alexa					1d		Resolved
Harshini*	SGMM393-226	client.events.1.onApplicationConnected failed in RDK shell				1d	2d	Resolved	Issue fixed
	SGMM393-865	RDKServices: onApplicationTerminated event is not triggering on killing westeros application.				1d	1d	Resolved	Issue fixed
	BCM72180-713	RDKServices: onApplicationConnected and onApplicationTerminated events are not triggering				1d	1d	Resolved	Issue fixed
	SGMM393-873	RDKServices: onError event is not triggering within the expected time range				1d	1d	Ready for Testing	Issue fixed
	BCM72180-706	RDKServices: RDKSHELL_SPLASH_IMAGE_JPEG variable is not defined in wpeframework.service				2d	1d	In Progress	Need to generalize the layer
	SGMM393-930	Deep sleep mode showed issues				1d	0.5d	In Progress	
	BCM72180-791	Deep sleep mode showed issues				1d	0.5d	In Progress	
	SGMM393-935	Blank screen is observed on trying to set screen resolution using org.rdk.RDKShell.1. setScreenResolution method					1d	In Progress	
	SGMM393-912	Few Systemd services are failed or in activating state					1d	Resolved	Issue fixed
Naveen*	SGMM393-623	avdecoderstatus showing idle instead of Active					2.5d	Ready for testing	
	BCM72180-681	avdecoderstatus showing idle instead of Active					2.5d	Ready for testing	

Engineer Name	Ticket Number	Title					Planned Estimate	Actual Effort	Status	Comments
	SGMM393-823	RDKServices: onAVDecoderStatusChanged event is not triggering with active status of audio/video pipeline changes						2d	Ready for testing	
	BCM72180-712	RDKServices: onAVDecoderStatusChanged event is not triggering with active status of audio/video pipeline changes						2d	Ready for testing	
Pragada*	BCM72180-375/ RDKVREFPLT-370	When RFC is disabled, able to disable the default interface in Broadcom device.						0	CLOSED	
	BCM72180-565/ RDKVREFPLT-427	[TDK][rdkservices][RDKV_CERT_AVS_Network]The expected result of Network_Toggle_WIFI_Interface_Status test is not correct						0	RESOLVED	
	SGMM393-938	[External BT Audio Streaming]Auto Connect didn't work after power cycling BT device						3d	READY FOR TEST	
	SGMM393-942/ BCM72180-802/ RDKVREFPLT-506	[TDK][FCS]Waymetric application is missing						3d	Awaiting FOr 3rd party	
	BCM72180-768/ RDKVREFPLT-475	Unable to control volume using Tatlow RDK universal remote control						0	RESLOVED	
	SGMM393-775	RDKServices: onUserInactivity Event is not getting triggered						2d	RESOLVED	
Sathish*	BCM72180-694	RDKServices: org.rdk.System.1. getNetworkStandbyMode is returning status as false					1.5d	0	RESOLVED	
	SGMM393-153	RDKServices: org.rdk.System.1. getNetworkStandbyMode is returning status as false					1.5d	0	RESOLVED	
	BCM72180-695	RDKServices: Cobalt - "Closure" Event is not triggering every time on Exiting from the Cobalt application					1d	0	InProgres	
	BCM72180-799	4K HLS stream is not playing fine via HLS player						4d	Ready For Test	working in latest image
	BCM72180-707	RDKService: "org.rdk.Wifi.1.getConnectedSSID" doesn't return connected SSID						4d	Inprogress	Manual is working , Waiting for TDK setup update

Note : * resources are buffer resources

Poland Team

Engineer Name	Ticket Number	Bug ticket	Blocker/ Critical	User Story	Support	Planned Estimate	Actual Effort	Comments	Title of the ticket	Status
Artur	SGMM393-610			Y		0.5	0.5	Retest with analysis provided. The SystemServices API seems to work. WOL does not wake the box.	WakeOnLAN(WOL) feature is disabled in Sagemcom	In Progress
Fryderyk	SGMM393-874	Y				4	4		RDKServices: Temperature related APIs are not returning proper response	Resolved
Fryderyk	SGMM393-873	Y				3	4		RDKServices: onError event is not triggering within the expected time range	Ready for testing
Fryderyk	SGMM393-871	Y				1	1		RDKService: Error in getting the SSID details from "org.rdk.Wifi.1. getConnectedSSID"	Ready for testing
Artur	SGMM393-181	Y		N		2	5	STANDBY, LIGHTSLEEP, DEEPSLEEP mapping with S1/S2 /S3 currently unclear. If S2 state is disabling the Thunder JSON-RPC, then the TC is invalid.	"onSystemPowerStateChanged" event is not getting triggered for ON state	Awatiing 3rd party
Fryderyk	SGMM393-494	Y							In Automatics [TC-STB-REBOOTREASON-003], Reboot reason is not obtained as OPS_TRIGGERED after reboot	Ready for testing
Artur	SGMM393-81	Y						Priority changed to minor	client.events.1.closure event failed for Cobalt	On hold
	BCM72180-618	Y							[PVS] Memory Usage is High while Video playback and plugin launch	New
Fryderyk	SGMM393-851	Y							Error while setting up the URL in WebKit browser /HtmlApp	Resolved

Artur	BCM72180-778	Y		N		1	1	Under review	Webkit's webinspector port duplication	Ready for testing
Fryderyk	SGMM393-896	Y				0	0		temperature threshold value not setting	Resolved
Artur	SGMM393-927	Y	Critical			1	1	CR created; Awaiting QA results	Intermittently, on reboot, VA UI is not loading	Ready for testing
Fryderyk	SGMM393-823	Y							RDKServices: onAVDecoderStatusChanged event is not triggering with active status of audio/video pipeline changes	Resolved
Artur	SGMM393-949	N	Major					Change rejected. Integration team should be responsible for setting LocalStorage before launching the App. Integration team has been notified.	Enable local storage in the HTMLApp instance	Closed

Adhoc tickets/User Stories :

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status

Bug Triage:

Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Status