RDK-V Sprint 10 Apr - 21 Apr

Team Capacity

Engineer Name	Total sprint velocity in days (10 days) [A]	Planned Leave /Holiday [B]	Default Velocity in days [A-B]	Backup Velocity in days for adhoc requests(1 days), If no adhoc requests this 1 days to be spent for a new Jira [C]	Scrum related activities(only for Scrum Master), Default 5 days and 1 day for individual contributor for their scrum activities [D]	Net velocity in days [A-B-C-D]
Sowmya	10	0	10	1	5	4
Rosna	10	1	9	1	5	3
Philip	10	1	9	1	1	7
Vijith	10	0	10	1	1	8
Janani	10	0	10	1	1	8
Balaji	10	0	10	1	1	8
Heam	10	0	10	1	1	8
Total Team Velocity	70	2	68	7	15	47

Sprint Planning Bug Tickets/User Stories :

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Update on this	Status
Sowmya	SGMM393-563	Runtime generation and download of container bundle		Y		10				
	SGMM393-568	[M4-W14] Run-time Containerization - OCI image generation				1		Subticket of SGMM393-563		COMPLETED
	SGMM393-569	[M4-W15] Run-time Containerization - Virtual box setup				1.5		Subticket of SGMM393-563		COMPLETED
	SGMM393-570	[M4-W15] OCI BundleGen Generation and Hosting it in HFS				1		Subticket of SGMM393-563		COMPLETED
Rosna	SGMM393-447	Youtube 2023 Integration		Y		3				COMPLETED
	SGMM393-559	Migrate to YT2023 by masking 2022								
	SGMM393-560	Verify encrypted playback-cenc								
	SGMM393-519	RDKServices: Wpeframework is in inactive state after reboot on setting device to LIGHT_SLEEP mode	Y			3				
Philip	BCM72180-366	[M4-W15]Support of Xdial feature for YT		Y		7				COMPLETED
Vijith	SGMM393-551	External audio support for SOC Build		Y		2				COMPLETED
	BCM72180-361	External audio support for SOC Build		Y		1				COMPLETED
	BCM72180-367	[M4-W15] Analysis of QAM -UVE via RMF		Y		2				COMPLETED
	BCM72180-368	Implementation and code-review QAM-UVE via RMF		Y		8				Ticket expected to be completed in next sprint
Janani	BCM72180-370	[M4-W15] Analysis of Common Android kernel		Y		2				COMPLETED
	BCM72180-371	[M4-W15] Implementation and code review of Android common kernel 64bit mixed mode				8				
	BCM72180-317	Kernel - Android Common Kernel 64 Bit Mixed Mode				2				COMPLETED
Balaji	SGMM393-553	[M4-W15]Reproduction of scenario - Unknown keypress	Y			1				COMPLETED

Owner	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort		Comments	Status
	SGMM393-554	[M4-W15] Analysis of the Unknown keypress	Y			2				COMPLETED
	SGMM393-555	[M4-W15]Implementation and code review	Y			3				
	REFPLTV-1720	[M4-W15]Updation of gstreamer sub components to 1.18.	Y			5				
Heam	BCM72180-292	RDK6 Bluetooth Voice remote integration		Y		5				COMPLETED
	BCM72180-335	Enable the Distros for getting voice support and compile build.				2			Sub-ticket of BCM72180-292	COMPLETED
	BCM72180-340	Tech4Home remote accommodation.				1			Sub-ticket of BCM72180-292	COMPLETED
	BCM72180-341	Test and Validate voice commands using tech4home remote				1			Sub-ticket of BCM72180-292	COMPLETED
	BCM72180-369	[M4-W15] Analysis of DTV session Manager via RMF		Y		2			Subticket of BCM72180-297	
	BCM72180-374	[M4-W15] Implementation and code review		Y		5			Subticket of BCM72180-297	
Rajapriya	SGMM393-423	Migration to 23.0 URSR SDK			Y	8				
	SGMM393-556	Integrate the changes for downloading the tar files from BCM partner central			Y	2			Sub-ticket of SGMM393-423	COMPLETED
	SGMM393-557	Create an image with SDk23 and all dependent tarballs			Y	4			Sub-ticket of SGMM393-423	COMPLETED

Adhoc tickets/User Stories :

Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status
SGMM393-398	Rialto support on BRCM		Y		3			COMPLETED
SGMM393-397	Rialto support on Sagemcom		Y					
SGMM393-503	Observing frame drop issue after seek operation	Y			2d for issue reproduction			
SGMM393-360	Could you please clarify if the following things are supported in Sagemcom?	Y			2			
SGMM393-424	RDK Service API is not responding more frequently during certification suite execution	Y			1			
SGMM393-436	RDK6 BLE Voice Remote Control			Y	8			COMPLETED
BCM72180-300	RDK6 IP - UVE AAMP							COMPLETED
BCM72180-332	Initial analysis - RDK6 IP - UVE AAMP				1		Subticket of BCM72180-300	COMPLETED
SGMM393-473	Try WV URL with YTS				1		Subticket of SGMM393-415	COMPLETED
SGMM393-415	Protected playback not working in YT23							COMPLETED
BCM72180-294	RDK6 Voice Stack				4			COMPLETED
SGMM393-438	RDK6 Voice Stack				4			COMPLETED
BCM72180-305	QT for BLE (OSS Version)							COMPLETED
SGMM393-450	RDK6 QT for BLE (OSS Version)							COMPLETED

Bug Triage:

Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Status
BCM72180 -34	Sometimes after boot up TV display is blank				RESOLV ED
BCM72180 -208	BCM Reference VA build HDMI Input tile is showing				RESOLV ED
BCM72180 -36	Unable to SSH to wlan0 IP				RESOLV ED
BCM72180 -256	Offline App URL when network disconnected is not working.				RESOLV ED
SGMM393 -88	Controller.1.status@WebKitBrowser is not returning expected results				RESOLV ED
SGMM393 -94	The methods org.rdk.System.1.getPreviousRebootInfo and org.rdk.System.1.getPreviousRebootInfo2 and org.rdk.System.1.getPreviousRebootReason fails to give proper output				RESOLV ED
SGMM393 -182	"org.rdk.System.1.reboot" method is not rebooting the device				RESOLV ED
SGMM393 -373	org.rdk.System.1.getPreviousRebootInfo2 is not returning the correct reason				RESOLV ED
SGMM393 -372	org.rdk.System.1.getRFCConfig is returning empty response for MEMORYSTATUS.FREE and MEMORYSTATUS.TOTAL				RESOLV ED
SGMM393 -179	HEVC streams playback is not working				RESOLV ED
SGMM393 -200	"getDiscoveredDevices" is not showing the available bluetooth device				RESOLV ED
SGMM393 -180	Video Progress position validation status is failing with Direct OGG				RESOLV ED
SGMM393 -142	Widewine protected video contents didn't play in youtube and testutility				RESOLV ED
SGMM393 -362	org.rdk.LoggingPreferences.1.isKeystrokeMaskEnabled is returning the value true after reboot				RESOLV ED
SGMM393 -432	RDK Services: empty results for the DeviceDiagnostics_Get_Configurations				RESOLV ED
SGMM393 -356	RDKServices : Bluetooth connection didn't work as expected				RESOLV ED
SGMM393 -399	wpeframework crashes frequently and box goes into hang state. Also corefiles fill the STB disk space				RESOLV ED
SGMM393 -357	RDKServices: Pairing status of bluetooth device doesn't persist after reboot				RESOLV ED