RDK-V W47 Sprint 20 Nov - 01 Dec

Team Capacity - 80

Engineer Name	Total sprint velocity in days (10 days) [A]	Holiday (1 day) [E]	Planned Leave [B]	Unplanned Leaves [F]	Default Velocity in days [A-B-E]	Backup Velocity in days for adhoc requests(1 days), If no adhoc requests this 1 days to be spent for a new Jira [C]	Scrum related activities(only for Scrum Master), Default 5 days and 1 day for individual contributor for their scrum activities [D]	Net capacity in days [A-B-E-D]
Sowmya	10	0	3		7	0	3	4
Rosna	10	0	2		8	0	4	4
Philip	10	0	0		10	1	1	9
Dinesh	10	0	0		10	1	1	9
Venkat	10	0	1		9	1	1	8
Balaji	10	0	1	1	9	1	1	8
Heam	10	0	6	4	4	1	0	4
Rajapriya	10	0	5		5	1	0	5
Rathi	10	0	9		1	0	0	1
Fryderyk	10	0	10		0	0	0	0
Shilpa	10	0	0	1	10	1	1	8
Harshini*	10	0	0		10	1	1	5
Naveen*	10	0	0		10	1	1	5
Pragada*	10	0	0	0	10	1	1	5
Sathish*	10	0	0	1	10	1	1	5
Total Team Velocity	150	0	37	7	113	11	16	80

*- Freshers are marked * against their name. Their bandwidth is calculated as 50%

Completed Story points - 35

Sprint Planning Bug Tickets/User Stories :

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status
Sowmya	BCM72180-262	DAC for YouTube Phase 1					1	BCM is not ready to merge the code.	Awaiting 3rd party
	SGMM393-968	RDKServices: [Intermittent] System plugin is not activating immediately after reboot	Y			2h			resolved
	BCM72180-800	Not Getting Video Player Ended Event for MVS EOS tests	Y			2	2		In Progress
	BCM72180-711	"onSystemPowerStateChanged" event is not getting triggered for ON state	Y					Followup	NA
	BCM72180-620	[PVS] Time taken for 'Destroy and Launch' is not within the expected range	Y			0.5	0.5		In Progress
	SGMM393-965	Back button is not working during video playback in Youtube					0.5	Minor	Ready for Testing
Rosna	BCM72180-838	Enable syslog-ng in BCM platform		Y		1		Minor/ UnderReview	In Progress
	RDKVREFPLT-263	[SGMM393-821] Validation of webkit 2.38 on rdk-next		Y		3		Need to raise CL to BCM layer	In Progress
	RDKVREFPLT-577	[SGMM393-821] Validation of webkit 2.38 on rdk6-main		Y		1			InProgress
	BCM72180-845	Webpa API call is not responding	Y			0.5			Resolved
	BCM72180-849	Video playback is not working through gst-launch with playbin3 on wpe-2.38 build	Y			0.5			InProgress

Name	ID	Description							Status
	BCM72180-841	Create RDK6 manifest for BCM 72180 & Sagemcom		Y		2			Resolved
Philip	BCM72180-839	Build error for HdmiCec_2 with thunder 4.2 enabled build		Y		1		Minor	NA
	BCM72180-840	WPE Browser Upgrade to 2.38.1 with thunder r4		Y		3	2	Minor	In Progress
	RDKVREFPLT-190	[BCM72180-307] WPE Browser Upgrade to 2.38 on rdk-next		Y		3	3		In Progress
	RDKVREFPLT-576	[BCM72180-307] WPE Browser Upgrade to 2.38 on rdk6-main		Y		2	2		In Progress
	CMFSUPPORT-1434	Create feature branch for thunder 4.2/Webkit 2.38.1 integration on rdk6-main for 6.1		Y		0	3		In Progress
Venkat	BCM72180-618	[PVS] Memory Usage is High while Video playback and plugin launch	Y			3	7		In Progress
	SGMM393-947	WPE 2.38 - Not possible to navigate in Tv Francaise app	Y			2		Minor /Deprioritized till WPE2.38 Integration Complete	NA
	SGMM393-921	WPE 2.38 - Video plays with higher speed than 1x	Y			3		Minor	NA
Dinesh	BCM72180-817	Encrypted content playback is not working on YouTube App (Non container mode)				5	4		Resolved
	BCM72180-774	Apparmor Profiles DAC Override Capability Issue					1	Followup	Resolved
	SGMM393-905	Apparmor Profiles DAC Override Capability Issue					0.5	Followup	Resolved
	SGMM393-966	[Apps Screen] Multiple issues observed in Apps	Y			1	0.5		Ready for Testing
	SGMM393-845	Video play related logs are not available	Y			1	0.5		Closed
	BCM72180-710	RDKService: Video play related logs are not available	Y			2	1	Minor	Closed
	BCM72180-697	RDKServices: org.rdk.Wifi.1.getCurrentState API is not returning the wifi states properly				0	0.5		Resolved
	BCM72180-844	RDK Services: Getting Empty reply from server error on activating OCIContainer Plugin					1		In Progress
Balaji	SGMM393-948	HLS playback with AAMP as source failing since nightly/20231018-dunfell	Y			3	2		In Progress
	SGMM393-933	Many of the Widevine encrypted stream URLS didn't play	Y			2	1.5		In Progress
	BCM72180-748	DRM streams are not playing				3	2.5		In Progress
	BCM72180-741	Video playback is not happening properly for seek and fast forward operations				0	1		In Progress
Heam	BCM72180-685	[TDK][BluetoothHal]Pairing to device is not persisted after reboot				2		Leave for whole sprint	NA
	BCM72180-544	[TDK][rdkservices] [RDKV_CERT_AVS_System] System plugin can't be activated in time after reboot				2		Leave for Whole sprint	Na
Rajapriya		Bringup of BCM972126OTT box					5		NA
Rathi	SGMM393-951/RDKVREFPLT-572	Failed to read Device.DeviceInfo.X_COMCAST-COM_STB_MAC using tr181	Y			1	1	Minor	In Progress
Shilpa	SGMM393-508	RDKService: 'ResidentApp MoveToFront' logs are not present in wpeframework.logs				1	0.5	Minor	Ready for Testing
	RDKVREFPLT-579	M11-W47 Bug Triage & Sanity Validation				5	5		Closed
	RDKVREFPLT-584	Sanity Validation on Thunder R4 Wpe-2.38.1 Dev build					2.5		Closed
Harshini*	BCM72180-816	Initially black screen displayed and after that screen resolution is not set when tried				1	1.5		In Progress

Owner	ID	Summary						Priority	Status
	SGMM393-935	Blank screen is observed on trying to set screen resolution using org.rdk.RDKShell.1.setScreenResolution method				1	1.5		In Progress
	BCM72180-619	[PVS] Time taken for 'Suspend and Resume' is not within the expected range				1	2		In Progress
	BCM72180-675	[FCA]: Localization.setTimeZone is returning error				1	1		Ready for Testing
	SGMM393-835	[FCA]: Localization.setTimeZone is returning error				0	1		Ready for Testing
	BCM72180-672	[FCA]: Default value is not available for Localization apis				1	1		Ready for Testing
	SGMM393-948	HLS playback with AAMP as source failing since nightly/ 20231018-dunfell				0	2		In Progress
Naveen*	SGMM393-508	RDKService: 'ResidentApp MoveToFront' logs are not present in wpeframework.logs				1	3	Minor	Ready for Testing
	BCM72180-621	PVS] Time taken for launch UI is not within the expected range				1	3	Major	In Progress
	DELIA-63780	[RDK6]: Yocto Version not matching with specified versions				2			NA
	SGMM393-133	The time taken for launching Main UI from another window is not within the expected limit				0	1	Minor	Closed
	BCM72180-661	Observing a blank screen during playback of featured VOD content after wpe-webkit 2.38 upgrade.				0	2	Minor	In Progress
Pragada*	BCM72180-671	[FCA]: Authentication.token type distributor is returning not supported				1	2	Major	Ready for Testing
	BCM72180-673	[FCA]: Parameters.Initialization throwing "Internal failure: NotFound" error				1	2	Major	Ready for Testing
	BCM72180-708	RDKService: The trip time is higher than threshold time				2	0.5	Minor	Ready for Testing
	BCM72180-654	Time Zone API is returning false response				1	0.5	Minor	Ready for Testing
	BCM72180-685	[TDK][BluetoothHal]Pairing to device is not persisted after reboot				0	1		Ready for Testing
	BCM72180-625	[PVS] Time taken for 'WebKitBrowser_TimeTo_ActivateDeactivate' is not within the expected range				0	2		In Progress
	SGMM393-922	Box is rebooting when setting power modes (Deepsleep) for alternate tries				0	1		In Progress
Sathish*	SGMM393-967	[External BT Audio Streaming]Audio not heard through Bluetooth sound bar after power cycle of Sound bar				1	2h		Ready for Testing
	SGMM393-778	Playback latency is larger than expected				3	0		NA
	SGMM393-970	Sagemcom build is failing in applying patch restart_wifi_after_deepsleep.patch				1	2		In Progress
	SGMM393-930	Deep sleep mode showed issues				0	2		In Progress
	SGMM393-229	setPowerState is returning false when the power state is set to ON after standby and getPowerState is returning UNKNOWN				0	1		In Progress
	BCM72180-711	onSystemPowerStateChanged" event is not getting triggered for ON state				0	2		In Progress
	SGMM393-181	onSystemPowerStateChanged" event is not getting triggered for ON state				0	1		In Progress

Poland Team : NA

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status

Bug Triage:

Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Status