

RDK-V Sprint 03 Jul - 14 Jul

Team Capacity - 73SPs

Engineer Name	Total sprint velocity in days (10 days) [A]	Holiday (1 day) [E]	Planned Leave [B]	Default Velocity in days [A-B-E]	Backup Velocity in days for adhoc requests(1 days), If no adhoc requests this 1 days to be spent for a new Jira [C]	Scrum related activities(only for Scrum Master), Default 5 days and 1 day for individual contributor for their scrum activities [D]	Net capacity in days [A-B-E-D]
Sowmya	10	0	0	10	0	5	5
Rosna	10	0	1	9	0	4	5
Philip	10	0	0	10	1	1	9
Vijith	10	0	0	10	1	1	9
Janani	10	0	0	10	1	1	9
Balaji	10	0	0	10	1	1	9
Heam	10	0	0	10	1	1	9
Rajapriya	10	0	0	10	1	1	9
Shilpa	10	0	0	10	0	1	9
Total Team Velocity	90	0	1	89	6	16	73

Total Leaves - 2SPs

Completed Story Points - 31.5SPs

Sprint Planning Bug Tickets/User Stories :

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Update on this	Status
Sowmya	BCM72180-570	Support for Code push for DAC Phase2.5			Y	1	2			Resolved
	SGMM393-452	wpewebkit 2.38 migration		Y		4	1			In Progress
Rosna	SGMM393-740	Disable Telnet/SSH in Sagemcom builds		Y		1	1			In Progress
	SGMM393-746	Disable all unused ports in iptables		Y		2				NA
	SGMM393-747	Disable TTY(serial console. SoC to support		Y		2				NA
	SGMM393-734	Automate DTB selection during Sagemcom image generation			Y			Followup		In Progress
Philip	BCM72180-559	Thunder4.2 Encrypted Stream playback		Y		5	6			FROZEN
	BCM72180-579	DAC integration with Thunder and validation		Y		4				NA
Vijith	BCM72180-574	Disable ssh/telnet in the prod builds		Y		1	0.5			Resolved
	BCM72180-575	Disable all unused ports in iptables		Y		2				NA
	BCM72180-576	Disable TTY(serial console. SoC to support)		Y		2				NA
	BCM72180-577	Disable ThunderUI		Y		2				NA
	BCM72180-578	Disable webInspect		Y		2				NA
Janani	BCM72180-566	Apps not launching on thunder4 branch with 3.10.16		Y		5	4			In Progress
	BCM72180-580	Validation of xcast, rdkservices, controller UI on thunder		Y		2				NA
	BCM72180-581	Validation and bug fixing of Alexa		Y		2				NA
Balaji	BCM72180-437	The iw misuse in function 'wifi_getRadioOperatingChannelBandwidth' in WiFi HAL	Y			0.5	0.5	Follow-up		In progress

	SGMM393-501	Unknown Keypress	Y			1.5	1.5	Follow-up		In Progress
	SGMM393-758	RDk6 Core Thunder r2 on Sagemcom		Y		9	2			Resolved
Heam	SGMM393-491	RDk6 Alexa Integration[Push to talk]				1	1.5			In Progress
	SGMM393-538	Unable to set the sound mode to DolbyDigital						Follow-up		NA
	BCM72180-297	RDk6 DVB (DTVKit) - Sessionmanager via RMF		Y		4	2			Resolved
	BCM72180-569	lib32-python3-pyobject-3.34.0-r0 do_package_qa error when we downgrade bluez to 5.48 version for alexa voice support.	Y			1				NA
	BCM72180-339	RDk6 Alexa Integration[Push to talk]				1	1.5			In Progress
	BCM72180-582	RDk6 Core Thunder r2 on BCM		Y		5[2]				NA
Rajapriya	BCM72180-538	Enabling Apparmor causing Video Freeze in BCM ACK5.15 URSR23.0.1	Y			1	1			Resolved
	SGMM393-728	Enabling Apparmor causing Video Freeze in SGC ACK5.15 URSR23.0.1	Y			1	1			Resolved
	SGMM393-744	Disable the apparmor for audiocapturemgr profile		Y		1				Resolved
	BCM72180-572	Disable the apparmor for audiocapturemgr profile		Y		1				Resolved
	SGMM393-726	Upgrade OCDM-Widevine and OCDM-Playready to latest release		Y		4				NA
	SGMM393-743	Protected content playback on thunder r4		Y		1				NA
Shilpa	BCM72180-585	Sanity & Feature Validation on Thunder 4.2 Image		Y		1	2			In progress
	SGMM393-750	Sanity & Feature Validation on Thunder r2 Image		Y		1	1			In progress
	BCM72180-283	RDk6 Reference UI 3.9 support		Y		1	0.5			In progress
	BCM72180-301	RDk6 Firebolt 1.0 release		Y		1	1			In progress
	SGMM393-751	[M7-W26]Bug Triage and Daily Sanity testing		Y		2	2			Closed
	SGMM393-752	Alexa [Push to talk] validation on BCM & SGM with BlueZ-v5.48		Y		2	2			In progress
	SGMM393-753	Sanity & Feature Validation on Wpe webkit 2.38 Image		Y		1	0			NA

NA

Adhoc tickets/User Stories :

Engineer Name	Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Planned Estimate	Actual Effort	Comments	Status
Sowmya	SGMM393-645	AAMP UVE API'S are returning response as undefined	Y			1	1		Frozen
Sowmya	SGMM393-700	M3, M4 and M5 Release planning and documentation			Y	1	1		Resolved
Sowmya	BCM72180-536	M3, M4 and M5 Release planning and documentation			Y	1	1		Resolved
Shilpa	BCM72180-595	Bp3 file request for Broadcom reference board			Y				In Progress
Balaji	SGMM393-614	DeviceIdentification plugin activation is failing in Sagemcom			Y	0.5	0.5		In Progress
Vijith	SGMM393-567	Success false shown in response for the curl command related to org.rdk.FrameRate.1.setCollectionFrequency in sagecom device	Y			0.5	0.5		READY FOR TESTING
Rosna	SGMM393-749	Disable weblnspect		Y		2	2		In Progress
Philip	BCM72180-593	Clear content playback with thunder r2		Y		1	3		Resolved
Sowmya	BCM72180-596	DAC functionality on thunder r2				3	1		Resolved
Janani	SGMM393-736	ERROR: broadcom-refsw-driver-unified-23.0-generic-rdk-r0 do_fetch: Fetcher failure: Fetch command export PSEUDO_DISABLED=1				1	1		Resolved

Heam	SGMM393-634	Unable to exit few Apps once launched on new UI-v3.9.48				1	1		Resolved
Vijith	SGMM393-758	Thunder r2 , Comcast/LGI CBCS changes, BCM adapter from thunder branch and clear content playback				1	1		Resolved
Shilpa	BCM72180-597	UI is not loading on recent DVB DTVkit URSR 23.0.1 ACK build				0.5	1	Verified by disabling lighttpd	Resolved
Vijith	SGMM393-766	Dac feature analysis on feature-cbcs-thunder42-integration-13062023 branch				1.5	1.5		Resolved
Vijith	BCM72180-608	Removal of unnecessary plugins				1	1		Resolved
Vijith	SGMM393-767	DAC on thunder-r4				3.5	3.5		In Progress
Heam	BCM72180-591	Bluetooth pairing is not happening in ACK builds for Bluez 5.48 version				6	6		In Progress
Rajapriya	BCM72180-603	Enabling audiocapturemgr profile causing Video Freeze in BCM ACK5.15 URSR23.0.1				1	1		In Progress
Rajapriya	SGMM393-762	Enabling audiocapturemgr profile causing Video Freeze in BCM ACK5.15 URSR23.0.1				0.5	0.5		In Progress
Rajapriya	SGMM393-765	Protected content playback on thunder r2				4	4		Resolved
Balaji	BCM72180-383	Few UVE_AAMP scripts are Failing				1	1		In Progress
Balaji	SGMM393-590	Change StartXdial.sh script in Sagemcom				1	1		In Progress
Balaji	SGMM393-539	Unable to populate SDK tool chain				0.5	0.5		In Progress
Janani	BCM72180-540	ERROR: ParseError at *****Broadcom_CMF/build-brcm972180hbc/conf/local.conf:247: Could not include required file conf/distro/include/###RDK_FLAVOR###.inc				2	2		Resolved
Philip	BCM72180-594	Encrypted content playback with thunder r2 +comcast/lgi CBCS changes				3	3		In Progress

Bug Triage:

Ticket Number	Title of the ticket	Bug ticket	User Story	Support	Status
SGMM393-715	WiFi Networks are not listing on recent SGM Images	Y			Resolved